

## IPMI Release Notes

*Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.*

<b>Product Name</b>	<b>X12DPT-B6</b>
<b>Release Version</b>	<b>01.02.44</b>
<b>Build Date</b>	<b>9/14/2022</b>
<b>Previous Version</b>	<b>01.02.35</b>
<b>Update Category</b>	<b>Recommended</b>
<b>Dependencies</b>	<b>None</b>
<b>Important Notes</b>	<b>None</b>
<b>Enhancements</b>	<b>None</b>
<b>New features</b>	<b>None</b>
<b>Fixes</b>	<ol style="list-style-type: none"><li>1. Removed System NIC (Systemslot, port) event description</li><li>2. Fixed wrong System NIC (Systemslot, port) event description</li><li>3. Fixed a backward configuration compatibility issue in 01.02.40</li><li>4. Fixed the order of the AOC Temp Sensors (they were out of order)</li><li>5. IPMI upload configuration message now changed</li><li>6. Fixed the NTP setting that is not syncing after BMC reboot, when setting invalid NTP server.</li><li>7. Fixed MARVEL and AOC card temperature missing.</li></ol>