

BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X12DPG-OA6
Release Version	1.4 SPS: 4.4.4.202
Build Date	08/23/2022
Previous Version	1.2
Update Category	Recommended
Dependencies	None
Important Notes	None
Enhancements	1. Updated Intel BKC to 2022_WW23(KIT #732569) PLR3, RC 2. Updated Intel BKC to 2022_WW23(KIT #732569) PLR3, SPS 3. Updated Intel BKC to 2022_WW23(KIT #732569) PLR3, ACM 4. Updated Intel BKC to 2022_WW23(KIT #732569) PLR3, SINIT 5. Updated Intel BKC to 2022_WW23(KIT #732569) PLR3, CPU 606A6 Microcode 6. Updated 2022_WW23(KIT #732569) PLR3, Intel VROC UEFI 7. Updated Intel BKC to 2022_WW23(KIT #732569) PLR3, Intel PMEM UEFI
New features	1. Add a BIOS option for PCIe enable/disable Link Retrain
Fixes	1. Fixed CPU2 information missing in the Setup.

Release Notes from Previous Release(s)

1.2 (04/17/2022)

1. Updated Intel BKC to 2021_WW52 (KIT #709738), RC
2. Updated Intel BKC to 2021_WW52 (KIT #709738), SPS
3. Updated Intel BKC to 2021_WW52 (KIT #709738), ACM
4. Updated Intel BKC to 2021_WW52 (KIT #709738), SINIT
5. Updated Intel BKC to 2021_WW52 (KIT #709738), CPU 606A6 Microcode
6. Updated Intel BKC to 2021_WW52 (KIT #709738), Intel VROC UEFI
7. Updated Intel BKC to 2021_WW52 (KIT #709738), Intel PMEM UEFI
8. Fixed an issue with CPU1 information that is missing in the Setup.
9. Increased MMIO high Size to 2TB for supported 10 NVIDIA GPU Cards.
10. Fixed the BIOSECO/IPMIECO Password setting Issue.

1.1b (11/10/2021)

1. Updated Intel BKC to 2021_WW39 (KIT #653811), RC.
2. Updated Intel BKC to 2021_WW39 (KIT #653811), SPS.
3. Updated Intel BKC to 2021_WW39 (KIT #653811), ACM.
4. Updated Intel BKC to 2021_WW39 (KIT #653811), SINIT.
5. Updated Intel BKC to 2021_WW39 (KIT #653811), CPU 606A6 Microcode.
6. Updated Intel BKC to 2021_WW39 (KIT #653811), Intel VROC UEFI.

1.1a (9/15/2021)

1. Changed BIOS Revision to 1.1a.
2. Updated Intel BKC to 2021_WW32 (KIT #645801), RC.
3. Updated Intel BKC to 2021_WW32 (KIT #645801), SPS.
4. Updated Intel BKC to 2021_WW32 (KIT #645801), ACM.
5. Updated Intel BKC to 2021_WW32 (KIT #645801), SINIT.
6. Updated Intel BKC to 2021_WW32 (KIT #645801), CPU 606A6 Microcode.
7. Changed HostResetWarningNotification settings.

1.1 (5/27/2021)

1. Changed BIOS Revision to 1.1.
2. Updated Intel BKC to 2021_WW15.
3. Added optimization for USB over LAN.
4. Added support to update BPS FW in BIOS.
5. Added support for OPROM control over Boot Mode.
6. Fix NVMe hot-plug issue.

Revision 1.0 (2020/1/27)

First release.