BMC Firmware Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. Al rights reserved.

Product Name	X12DPG-QR
Release Version	1.02.51
Build Date	11/29/2022
Previous Version	1.02.23
Update Category	Recommended
Dependencies	None
Important Notes	None
Enhancements	 New support Intel GPU ATS M1 and ATS M3 Improvement Item PSU Fan 2 = 0 RPM on IPMI WEB Support GPU NVIDIA RTX A2000-12G, RTX A4500 and RTX A5500
	1. Support AOC-STGC-i2
	2. Support iKVM New UI
	3. Add NIC link up/down event
	4. New error message now displays in Dynamic DNS, Floppy Disk, and
	IPMI Configuration
	5. Support Intel VROC feature
New features	6. Support IPMI Lan disable
	7. Special Characters Allowed in SNMPv2 Community String
	8. Added Alert Notification for SNMP
	9. WebUI will show "Invalid Username or Password" with new created
	user which contains special characters in username
	10. Support AIOM AOC-ATG-B2TM
	11. Convert prefix to string type before checking duplicate rule

- 1. Fix Login screen should be support "eye-icon" button to view password.
- 2. Fix IPMI Web Network page "DHCPv6" check fail
- 3. Fix Added warning message for RAID HDD type mixing
- 4. Fix automation test failed, test case 408: BMCWebUI
- 5. Fix SMTP User Name now supports @ and .
- 6. Fix remove license key check in system troubleshooting webui page
- 7. Fix The LED blink/unblink action take too long time
- 8. Fix Error Message Display Behaviors and MELs were added
- 9. Disable LED blink action on physical and logical view pages for M.2 cards.
- 10.Fix redfish SNMP patch protoeolenable and port fail SNMP Cannot Turn On"
- 11. Fix missing fan control for ACC ASICx Temp
- 12.Fix WEBUI to allow the user to edit user properties in FW 1.00.00
- 13. Fix Memory Thermal Trip display Error
- 14.Fix BIOS recovery hang from WEBUI Fix not to show tips while saving on "Modify Community String" without any special characters
- 15.Fix IP Access Control drops Host Interface, causing System Brick
- 16.Fix Redfish automation test failed w/8 failures on v01.02.23
- 17.Fix Pressing the Mount button in HTML5 iKVM Virtual Media with no file selected will prevent mounting
- 18.Fix [Web Function] Login User Privileges account; It should be disable while Connection Protocol and Authentication on SMTP
- 19. Fix MEL log non-existent user delete action
- 20.Fix AOC-AG-i4M the i350 does not support sensor but the WEB UI show sensor status.
- 21. Fixed After BMC load default, SMCIPMITool cannot clear sel
- 22.Fix iKVM(JAVA plug-in) to support "IMA" image
- 23.Fix "Export to Excel" button is not deactivated when all Maintenance Event Log categories are deselected
- 24.Fix Fields name mismatch SPEC of Authentication/Encryption key and Protocol. (Alert/SNMPv3)
- 25.Fix graphics missing in Power webpage; Power graph on IPMI WebUI issue
- 26.Fix Memory thermal trip display error
- 27.Fix detectable version of power supply under BMC Web GUI
- 28.Fix BMC webUI directory service to Active Directory page not matching X12 UI help spec.
- 29.Fix Found the AutoConfiguration error when executed; Change LAN via BMC configuration" with ATT 2022/04/27"
- 30.Fix Automation tests Failure, Redfish automation test failed w/ 8 failures on v01.02.23 IPMI ECO automation test failed
- 31. Fix Ignore query string if it's longer than 128 bytes
- 32.Fix Error message is incomplete when delete user while it is logged in. Task list filter Completed Time The string will be shifted. It should be using
- "Community String/Access Mode" on SNMPv2.

33. Fix - Active Directory doesn't match SPEC define.

- 34. Fix SAS controller make WEBUI Firmware inventory hang in 01.02.25
- 35.Fix no GPU-NVQT400-LK sensor and GPU information on WEB UI
- 36. Fix Time zone not reset to default after disable NTP through redfish
- 37.Fix Some Event log time zone is incorrect

Fixes

38. Fix - Redfish automation test failed.

39.Fix - "Anonymous" user should be preserve while filter account type "Redfish/IPMI" or "SNMP", "Export to Excel" button is not deactivated when all Maintenance Event Log categories are deselected

40. Fix - not allow the user to log in with created user using ipmicfg

41.Fix - Unable to mount "Floppy Disk" while upload the *.ima file.(Virtual Media); Sorting result was incorrect by "Prefix Length" on "IP access Control" page; It should be set to required field and with * symbol on "Syslog Server" and "Port"; - Dynamic DNS feature has different filter rule between H12 and X12. "Account Type" is not match on Add/Modify window and user list. Mount *.img display wrong file type on Virtual Media page; Unable to mount "Floppy Disk" while uploading the *.ima file.(Virtual Media)

42.Fix - Ignore question mark if no query parameter is appended to 43.Fix Redfish URI - IPMICFGECO failed on TC122- SUMECO failed on TC373 44.Fix - It should be hide star* symbol with Community String; It should be using "Community String/Access Mode" on SNMPv2; "Account Type" doesn't match on Add/Modify window and user list; It should not present duplicated information on "Add New User" window. It should not show tips while saving on "Modify Community String" without any special

45.Fix - CPLD version display is not match between existing version and new version on Update CPLD Step 3

46.Fix - User/Operator privileges should be able to modify itself while logged in; Password tips behavior is incorrect on "Add New User/Modify User" window; Auth key/Private key change password icon is inconsistent with Password field. (Add New User); Tips info is shift the position of Password and Confirm Password field. (Add New User); Tips info is overlap on "Account Type" check box. (Add New User)

47. Fix - Disabled the function when system lockdown enable

48.Fix - NTP can still using localhost as Primary NTP Server; It should not allow add empty Community Strings.(SNMPv2)

49.Fix - Apply common issues reported in other projects. Remote iKVM session have probability disconnect by Power control action; Virtual CD-ROM can input invalid symbol to "User" and "Password"; Error Message Display Behaviors and MELs were added; Upload invalid license key will not generate unsuccessfully MEL event log; Fan page Heavy I/O Speed mode name check fail; Abnormal behavior after generating more health event log and Mark/clean Acknowledged.

50.Fix - GPU page item name check fail; Network page "DHCPv6" check fail; BMC IP sometime incorrect; IPMI Web - Generate user account with 20 characters password fail. [146098] - Should be forbidden input .(dot) when set service port number; [GUI] Display "System Lockdown Mode is on" is more exactly when it's on going; It should be forbidden input decimal point value at "Host IP Address"; It should be disable "IMG/IMA Image" function once "ISO Image" already mounted on same Device; It should be forbidden input decimal point value at "Host IP Address"; Mount ISO fail behavior abnormal while clicking on "Failure message"; Incorrect MEL after changing Rollback ID setting. [ENGINEERING] - fix update nic shows target fail in WEBUI; Abnormal behavior once visit other page and then back to Network page; Extra space in the error message "Failed Login Counter Reset value cannot be greater than Account Lockout Duration." Incorrect MEL after saving

network page; Severity is not right when the license key uploaded unsuccessfully; [Samsung PM1743-IPMI] "Percentage drive life used" shows as 0% for Samsung PM1743 device.

51.Fix - [GUI] Destination Address of Alert(Redfish) tips is overlap.

52.Fix - Should have "*" if the blank is required to fill in. (Dynamic DNS Server Address and BMC Hostname). [ENGINEERING] - support NVIDIA GPU A800 80GB.

53.Fix - Apply common issues reported in other projects. BMC WEB format is sometimes out of shape, Input exist "Port number" should not return Oops! error message. Not to allow user to enter space when modifying User's SNMPv3 Encryption key and Authentication Key; Some of Descriptions on MEL page don't have Event ID; Should have * if the blank is required to fill; Severity should not be green when an Image is mounted unsuccessfully; Incorrect MEL after setting SMTP User Name; SNMP Authentication and Encryption key length maximum does not meet requirement; [DVT]AIOM"AOC-ATG-i2TM" Healthy Status not follow the PLDM spec check; Typo on iKVM; IPMI Config failed upload message modified

54.Fix - remove System NIC(Systemslot, port) event description

54.Fix - Temove System Nic(Systemsiot, port) event description

55. Fix - configuration backward compatible issue in 01.02.40

56. Fix - set correct max alert count to 15

57. Fix - the order of the AOC Temp Sensors is out of order

58. Fix - IPMI upload config message now changed

59.Fix - NTP setting not sync after BMC reboot when setting invalid NTP server.

60.Fix - User/Operator privileges should be able to modify itself while logged in

61.Fix - Incorrect Severity under MEL

62. Fix - Error message after modifying Web port and Web SSL port

63.Fix – Virtual Media/Record/Full-Screen help content is not match with spec.

64.Fix - Different status messages when configuring Virtual Media and DDNS

65.Fix – Fail to install OS by virtual media HTML5 sometimes

66. Fix - Error msg is incorrect when disable in session user.

67.Fix - ipmi lan vlan value is not expected. Vlan ID value is not match with spec.

68.Fix – HTML5/Java iKVM show wrong message when update IPMI firmware in old/new UI iKVM; [Ikvm] Protocal won't disconnect when update IPMI.

69.Fix - GUI -- Display icon color is incorrect when mount success

70.Fix - VROC info does not show in Redfish.

71.Fix - ECO --22058 -- 01.02.33 --[iKVM] Virtual keyboard language won't sync with iKVM language.

72.Fix - Enable I2C protection

73. Fix - Blink/Unblink action does not show in check list

74.Fix - 'NIC Temp' is 'N/A' in IPMI WebGUI sensor reading page. Dedicate LAN LED is not blinking while BMC works fine

75.Fix - Apply common issues reported in other projects. Remote iKVM session have probability disconnect by Power control action. Virtual CD-ROM can input invalid symbol to "User" and "Password"; Error Message Display Behaviors and MELs were added. Upload invalid license key will not generate unsuccessfully MEL event log. Fan page Heavy I/O Speed mode name check

fail. Abnormal behavior after generating more 2076 health event log and Mark/clean Acknowledged. GPU page item name check fail. Network page "DHCPv6" check fail. BMC IP sometime incorrect. IPMI Web - Generate user account with 20 characters password fail. Should be forbidden input .(dot) when set service port number. [GUI] Display "System Lockdown Mode is on" is more exactly when it's on going. It should be forbidden input decimal point value at "Host IP Address". It should be disable "IMG/IMA Image" function once "ISO Image" already mounted on same Device. It should be forbidden input decimal point value at "Host IP Address" Mount ISO fail behavior abnormal while clicking on "Failure message" Incorrect MEL after changing Rollback ID setting.

76.Fix - update nic shows target fail in WEBUI. Abnormal behavior once visit other page and then back to Network page. Extra space in the error message "Failed Login Counter Reset value cannot be greater than Account Lockout Duration." Incorrect MEL after saving network page. Severity is not right when the license key uploaded unsuccessfully. [Samsung PM1743-IPMI] "Percentage drive life used" shows as 0% for Samsung PM1743 device. [GUI] Destination Address of Alert(Redfish) tips is overlap. Should have "*" if the blank is required to fill in. (Dynamic DNS Server Address and BMC Hostname). Fix - support NVIDIA GPU A800 80GB.

77.Fix - Cannot set the SNMP IP as 0.0.0.0 on X12DGQ-R even though the BMC WEBUI's SNMP destination address setting has already been changed to 0.0.0.0

78.Fix - Change the response data of IPMI OEM command - Get OTP board serial number to align withe new IPMI command format

79.Fix - Integrate new DDR4 driver to improves timing and signal quality in AST2600.

80.Fix - Update network hostname format

81.Fix - Add the network AOC inserted WebUI

82.Fix - Redfish method to set BMC LAN interface

83.Fix - It should be forbidden input decimal point value at "Host IP Address"

84.Fix - Username should not allow "!" which is not match with spec

85.Fix - "Duplicated rule" prompt message and behavior is not same as X12 UI SPEC define.

86.Fix - Prevent unspecified address and loopback address are added to static IPv6 addresses

87.Fix - SMCIPMITOOLIPMITOOL and WEB have different naming of power supply in inventory items

88.Fix - Doesn't show any popup message when press down reload button without BMC configuration file

89.FixBMC_not_displaying_capacity_for_Kioxia_CD6_drive_in_BMC_WebGUI 90.Fix - Error HTTP message format at X13 and X12 redfish (/redfish/{string}.IKVM)

91.Fix- No MEL is generated when attempting to login with wrong password on Web

92.Fix - It should not pop up warning message when add difference "Policy" with same IP/Prefix Length.

93. Fix - The password for factory setting should be unique password.

94.Fix - The frame of "SNMPv2" help window is not complete at right hand side (Japanese)

95.Fix - Some Event log time zone is incorrect and not follow the latest MEL
SPEC
96.Fix - when NTP disable, user cannot modify timezone from WEB.
97.Fix - Enable StatelessAddressAutoConfig in Redfish ethernetInterface
98.Fix - Set HTML5 console as default selection
99.Fix - IPv6 auto-config option will be enabled after set others network
parameters