BMC Firmware Release Notes

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X13SEM-F_TF
Release Version	1.00.25
Build Date	1/4/2023
Previous Version	1.00.18
Update Category	Recommended
Dependencies	None
Important Notes	None
Enhancements	When the NTP is disabled, the user cannot modify the time zone from WEB.
New features	Use the Redfish method to set the BMC LAN interface.
Fixes	Removed rollback ID configuration page. The rollback ID always
	updates when updating the firmware.
	2. Lost PFR image version on the web.
	3. Enable StatelessAddressAutoConfig in Redfish ethernetInterface.
	4. Set HTML5 console as the default selection.
	5. The IPv6 auto-config option will be enabled after setting other
	network parameters.
	6. Fixed the change BIOS password failure.