

IPMI Firmware Release Notes

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X13SEW-F/TF
Release Version	01.00.43
Build Date	1/31/2023
Previous Version	01.00.28
Update Category	Recommended
Dependencies	None
Important Notes	None
Enhancements	N/A
New features	1. Upload wrong "SAS3916" firmware file, should not enter update process. 2. Remove sensor "PMEM Temp" on X13SEW and X13SEI by PM's request
Fixes	1. Compatible with X13SEW BIOS FWUP 1.0a 2. Can't get system log on syslog 3. WebGUI CPU Speed info feature broken in 01.00.39 4. Disable TLSv1.0 and TLSv1.1