

IPMI Firmware Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	H13SSW
Release Version	01.00.14
Build Date	2/10/2023
Previous Version	01.00.06
Update Category	Recommended
Dependencies	BIOS 1.1
Important Notes	ECO# BMC_H13AST2600-ROT-1401MS_20230210_01.00.14_STDsp.bin - BMC Image BMC_H13AST2600-ROT-1401MS_20230210_01.00.14_STDsp.zip - BMC image and flash utility package
Enhancements	1. Fixed NVMe eject/insert glitches. 2. Fixed the problem of SMBUS reading and writing an NIC card.
New Features	N/A
Fixes	1. Fixed incorrect power status 2. Fixed the error of MEL display ID 0xd6 after BIOS was updated. 3. Fixed the issue with the task messages failing to display when BIOS update was complete. 4. Fixed the incorrect display of DIMM names when DIMMs were inserted from slot G1 to F1.

Release Notes from Previous Release(s)

01.00.06 (2022/11/15)

First release.