

# IPMI Firmware Release Notes

*Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.*

<b>Product Name</b>	<b>X12SPG-NF</b>
<b>Release Version</b>	<b>00.23.77</b>
<b>Build Date</b>	<b>1/17/2023</b>
<b>Previous Version</b>	<b>00.23.70</b>
<b>Update Category</b>	<b>Recommended</b>
<b>Dependencies</b>	<b>None</b>
<b>Important Notes</b>	<b>None</b>
<b>Enhancements</b>	<b>N/A</b>
<b>New features</b>	<b>N/A</b>
<b>Fixes</b>	<ol style="list-style-type: none"><li>1. Automation test has failed three times.</li><li>2. Redfish test has failed once.</li><li>3. No related MEL when set up Active Directory (either setup by SMCIPMITOOL).</li><li>4. Network vlan Tag does not match with WEB and SMCIPMITOOL.</li><li>5. The content of help under System Crash Dump does not match with the behavior.</li></ol>

	<ul style="list-style-type: none"><li>6. BMC SEL Log will show "PSU Status" during the DC on/off cycles.</li><li>7. Fixed the broken provisioning feature.</li><li>8. Fan issue.</li><li>9. [147111] OEM--Beiliande--19018--11.01.26 (09/30/2022) -- AD username should be displayed completely. [146107] ECO--19176--00.14.06 (08/18/2022) -- AD username should be displayed completely.</li><li>10. BMC function will not work if there is no LAN cable connected to the dedicated port.</li><li>11. Cannot auto power on SUT after updating the golden BIOS FW.</li></ul>
--	---