BMC Firmware Release Notes

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X13SET-G(C)				
Release Version	1.00.11				
Build Date	3/2/2023				
Previous Version	N/A				
Update Category	Recommended				
Dependencies	None				
Important Notes	None				
Enhancements	None				
New features	None				
	BMC GUI fan speed Low critical wrongly displayed.				
Fixes	2. [Web Function] VLAN ID default value should be preset to 1 and not empty.				
	3. [Redfish] failed to successfully change mode to BMCNM.				
	4. System keeps rebooting with POST message "PEI—IPMI Initialization" after AC				
	cycle.				
	5. Network AOC item was not present in the web GUI page.				
	6. Information of AOC-A25G-i2SM displayed abnormally in the BMC web UI.				
	7. Health Status/Sensor reading/Link Status cannot be identified after updating to				
	BIOS 20230224.				