

## BIOS Release Notes Form

*Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.*

<b>Product Name</b>	<b>X13DSF-A</b>
<b>Release Version</b>	<b>1.1a</b>
<b>Release Date</b>	<b>03/07/2023</b>
<b>Previous Version</b>	<b>1.1</b>
<b>Update Category</b>	<b>Enhancement</b>
<b>Dependencies</b>	None
<b>Important Notes</b>	None
<b>Enhancements</b>	<ol style="list-style-type: none"><li>1. Updated Intel BKC 2023_WW09, Intel RC Version 9409.P31 MR2 and HBM PV.</li><li>2. Updated SPS 6.0.4.33.</li><li>3. Updated 806F8 Intel(R) Processor SPR E-Stepping micro code 2B0001B0.</li><li>4. Remove AOC Lan mac from BMC dashboard.</li></ol>
<b>New features</b>	None
<b>Fixes</b>	<ol style="list-style-type: none"><li>1. Corrected smbios type 17 Device Locator strings.</li></ol>

**Release Notes from Previous Release(s)**

**1.0 (10/28/2022)**

*Initial release.*

**1.1 (01/19/2023)**

1. Updated to 5.29\_EagleStreamCrb\_0ACOR\_071 and SPS 6.0.4.25.
2. Updated Intel(R) Processor SPR E-Stepping microcode 2B000161.
3. Expose "CXL Security Level" and "CXL Header Bypass" for CXL.
4. Regular Improvement.

**1.1a (03/07/2023)**

5. Updated Intel BKC 2023\_WW09, Intel RC Version 9409.P31 MR2 and HBM PV.
6. Updated SPS 6.0.4.33.
7. Updated 806F8 Intel(R) Processor SPR E-Stepping micro code 2B0001B0.
8. Remove AOC Lan mac from BMC dashboard.
9. Corrected smbios type 17 Device Locator strings.