

# BIOS Release Notes Form

*Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.*

<b>Product Name</b>	<b>X12SPT-G</b>
<b>Release Version</b>	<b>1.4b</b>
<b>Release Date</b>	<b>01/20/2023</b>
<b>Build Date</b>	<b>01/20/2023</b>
<b>Previous Version</b>	<b>1.4a</b>
<b>Update Category</b>	<b>Recommended</b>
<b>Dependencies</b>	<b>None</b>
<b>Important Notes</b>	<b>None</b>
<b>Enhancements</b>	<ol style="list-style-type: none"><li>1. Updated 5.22_WhitleyCrb_0ACMS_ICX_74 Intel BKCWW46 IPU2023.1, please check header for firmware revisions.</li><li>2. Updated Intel Server Platform Services for Whitley Server Platforms IPU2023.1 4.4.4.301.</li><li>3. Update VROC SATA/sSATA EFI driver to VROC PreOS v7.8.0.1012.</li></ol>
<b>New features</b>	<b>None</b>
<b>Fixes</b>	<ol style="list-style-type: none"><li>1. Fixed an issue where memory errors were not being reported in the SMBIOS event log.</li><li>2. Fixed system exception problem.</li></ol>

## **Release Notes from Previous Release(s)**

### **1.4a (12/17/2022)**

1. Updated 5.22\_WhitleyCrb\_OACMS\_ICX\_74 Intel BKCWW46.
2. Updated the VROC SATA/sSATA EFI driver to VROC PreOS v7.8.0.1012 to address Intel Virtual RAID on CPU (VROC): Data Loss Exposure Due to RAID 5 TRIM.
3. Moved AF workaround code to address the issue where the system is stuck in 0xAF power cycling when executing update golden image.
4. Updated the DBX file to fix Secure Boot Bypass issue.
5. Updated the template v1.1\_20220809.
6. Updated the BPS UEFI driver to 02.00.00.3887 for IPU2022.3.
7. Followed the SMBIOS template sync the chassis type from FRU0 to SMBIOS Type 03. Removed ignore sync up SMBIOS Type 03 when the chassis type is unknown or other.
8. Updated Intel Server Platform Services for Whitley Server Platforms IPU2023.1 4.4.4.301.
9. Updated the signal value for AOC-GTG-B2T.

### **1.4 (07/12/2022)**

1. Updated SmcOOB to the version "\_SMCOOBV1.01.25\_" to fix unexpected system-resetting when loading NVRAM defaults.
2. Updated 5.22\_WhitleyCrb\_OACMS\_ICX\_72.1 Intel BKCWW23 PLR3.
3. Updated VROC SATA/sSATA EFI driver to VROC PreOS v7.7.6.1004 to address INTEL-TA-00692. CVE-2022-29919(7.8 High), CVE-2022-30338(6.7 Medium), CVE-2022-29508(6.3 Medium), CVE-2022-25976(5.5 Medium)
4. Added IPMI PXE boot support to all LAN ports, for both Legacy and UEFI PXE.
5. Added Link Retrain per port in the BIOS.

### **1.3 (05/12/2022)**

*First release.*