## **BMC Firmware Release Notes Form**

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X12DPI-NT6
<b>Release Version</b>	1.01.39
Build Date	02/28/2023
<b>Previous Version</b>	1.01.24
Update Category	Recommended
Dependencies	None
Important Notes	None
Enhancements	<ol> <li>Modified Dedicated Link options: Added 1G Full and removed 10M Half/Full except X12STD-F and X12STE-F.         <ul> <li>a) X12STD-F Dedicated Link is fixed in Auto Negotiation.</li> <li>b) X12STE-F Dedicated Link is fixed in 1G Full.</li> </ul> </li> <li>Improved the stability of BIOS-related ROT operations.</li> <li>Runtime i2c protection failed.</li> </ol>
New features	1. Added i2cmap protection review.
Fixes	1. UI Special Characters specs do not define the VROC Virtual Drive name.
	2. [Web Function] Web GUI fails to display SATA VROC.
	3. Avoided ME hang during BIOS-cloning-GOLDEN operation.
	<ol> <li>RAID can't be deleted back once set up and the trash bin field will be grayed out in IPM.</li> </ol>
	5. MEL's description does not match what is shown in the specs.
	6. Disabled TLSv1.0 and TLSv1.1.