

BMC Firmware Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X12DHM-6
Release Version	01.01.43
Build Date	4/26/2023
Previous Version	01.01.38
Update Category	Recommended
Dependencies	None
Important Notes	None
Enhancements	1. Improved compatibility with IPMIECO TC0002, 2036, TC2063,TC2076.
New features	
Fixes	<ol style="list-style-type: none">1. Fixed-[155400] [Solidigm D5-P5430][BMC 01.00.17] IPMI WebGUI Storage Monitoring did not show drive information.2. Fixed-[155644] ECO -- 20899 -- 01.00.48 -- [MEL] MEL log Description not quite matching with SNMPv3 Auth Protocol/Private Protocol.3. Fixed [155126] ECO -- 18379 -- 01.01.11 -- DDNS unable to send multiple requests simultaneously causing switchers out of shape.4. Fixed [152359] STD -- 16914 -- 01.01.38 (2023/01/04) -- Radius packet not following RFC28655. [153419] STD -- 17212 - 01.00.42 - [Security] Global buffer read overflow at X13 and X12 redfish (/redfish/v1/Chassis/NVMeSSD.0.Group.0.StorageBackplane/Drives/Disk.Bay.{num}).6. Fixed-[155021] Network IPv6 saving DNS Server IP as blank reverts to previous value; Auto Configuration failed to switch on once switch off.7. Fixed-[154317] ECO -- 21603 -- 01.00.15(02/24/2023) -- Function-- Able to click blink or insert HDD button when system lockdown mode. [153387] ECO -- 18380 -- 1.01.11 --

	<p>System Lockdown SystemLockdown Storage Monitoring Physical View Eject / Insert button not disabled.</p> <p>8. Fixed-[153407] ECO--20899--01.00.44(02/03/2023)—It was conflict checking rule on "Remote User" and "Remote Groups" while clicking on "Save" button in AD/LDAP.</p> <p>9. Fixed-[154392] U2_SSD temperature did not reflect the hottest sensor reading on IPMI.</p> <p>10. Fixed-[152308] STD -- 16914 -- 01.01.38 (2023/01/04) -- Syslog packet not following RFC3164 Copy Project Issue Link.</p> <p>11. Fixed-[154316] ECO -- 21603 -- 01.00.15(02/24/2023) -- Function- - Syslog packet not following RFC3164.</p> <p>12. Fixed-[154318] ECO -- 21603 -- 01.00.15(02/24/2023) -- GUI -- No popout error message when typing the wrong string at SNMPv2 Name field.</p> <p>13. Fixed-[155731] Redfish Automation 1 failed.</p> <p>14. Fixed-[155021] ECO -- 16914 -- 01.01.41 -- Network IPv6 saving DNS Server IP as blank reverts to previous value; Auto Configuration failed to switch on once switch off.</p> <p>15. Fixed [152604] Redfish Automation has 4 failures.</p> <p>16. Fixed- to disable TLSv1.0 and TLSv1.1.</p> <p>17. Fixed- [151066] STD -- 20122 -- 01.13.08 -- Sensor naming not matching with sensor specification.</p>
--	---