IPMI Firmware / BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	H13SSH			
Release Version	1.1c			
Release Date	07/13/2023			
Previous Version	1.1a			
Update Category	Recommend			
Dependencies	N/A			
Important Notes	ECO #28400 BIOS Image: BIOS_H13SSH-1C9F_20230713_1.1c_STDsp.bin BIOS Update Package: BIOS_H13SSH-1C9F_20230713_1.1c_STDsp.zip Please update BIOS with attached Flash Utility in package.			
Enhancements	 Under the BIOS setup menu, check "BIOS Version" reports version 1.1. AMD ucode patch 2 to fix for erratum #1480. Check microcode version. 			
New features	N/A			
Fixes	 Plug in Broadcom NIC in AIOM1. Verify that the bifurcation is correct for the AIOM. Fix issue where XILINX U50 would hang. Fix issue where XLINX U50 link width would occasionally drop. Fix issue where video would be unusable under certain conditions. Add workaround for Micron 6500 lane drop issue. Set AST2600 VGA to be Gen2. 			

Revision 1.1a (05/26/2023)

- 1. Apply AGESA 1.0.0.7 and Patch.
- 2. Improve 1st boot time for 2DPC.
- 3. Fixed ACPI USB mapping.
- 4. Reworked 2U24 slot mapping.
- 5. Fixed issue where Micron 7450 drives would degrade during on/off test.
- 6. Fixed issue where configuration could not be detected after AC cycle.
- 7. Fixed issue where AMD related BIOS settings could not be changed by SUM.

1.0 (03/29/2023)

First release