## **IPMI Release Notes**

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

| Product Name        | X12SPL-(LN4)F  |
|---------------------|--|
| Release<br>Version  | 1.03.05  |
| Build Date          | 9/4/2023   |
| Previous<br>Version | 1.01.45  |
| Update<br>Category  | Recommended  |
| Dependencies        | None   |
| Important<br>Notes  | None   |
| Enhancements        | None   |
| New features        | <ol> <li>Support IPv6 enhancement spec.</li> <li>Uploaded invalid Device 0 file help tip overlaps when zoomed in to 125 percent with 14 inches and 175 percent and 200 percent with 22 inches.</li> <li>Health status of task list is not complete when zoomed in from 75 percent to 200 percent.</li> <li>DDNS upload invalid key help tip overlaps when zoomed to 200 percent.</li> <li>NTP server error message will exceed the frame and overlap with the side bar when zoomed in from 100 percent.</li> </ol> |

| Fixes | <ol> <li>Downgraded from BIOS 1.3 to BIOS 1.1. BIOS is shown correctly, but<br/>IPMI web still shows BIOS 1.3.</li> <li>BMC version is incorrect in troubleshooting Log.</li> <li>HDD info lines are not aligned at Physical View.</li> <li>Redfish Hostname special characters support.</li> <li>Downgraded from BIOS 1.5 to BIOS 1.1. BIOS is shown correctly, but<br/>IPMI web still shows BIOS 1.5.</li> <li>Updated BIOS will show message about "backup and golden image<br/>undetell vie Web III.</li> </ol> |
|-------|---|
|       |   |