

IPMI Release Notes

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X12SPO-(NT)F
Release Version	01.03.05
Build Date	9/4/2023
Previous Version	01.01.34
Update Category	Recommended
Dependencies	None
Important Notes	None
Enhancements	<ol style="list-style-type: none">1. Syslog packet did not follow RFC3164 Copy Project Issue Link.2. Modified Dedicated Link options: Add 1G Full and remove 10M Half/Full except X12STD-F and X12STE-F. X12STD-F Dedicated Link is fixed in Auto Negotiation. X12STE-F Dedicated Link is fixed in 1G Full.
New features	<ol style="list-style-type: none">1. Uploaded invalid Device 0 file help tips is overlapped when zoomed in to 125 percent with 14 inches and 175 percent and 200 percent with 22 inches.2. Health status of task list is not complete when zoomed in from 75 percent to 200 percent.3. DDNS upload invalid key help tips is overlapped when zooming to 200 percent.

	<p>4. NTP server error message will exceed the frame and overlap with the side bar when zoomed in from 100 percent.</p>
Fixes	<ol style="list-style-type: none"> 1. MEL log Description did not quite match SNMPv3 Auth Protocol/Private Protocol. 2. Successfully deleting IPv6 DNS will always create a "IPV6 DNS server 0:0:0:0:0:0:0 was deleted unsuccessfully" entry in the Maintenance Event Log. 3. DDNS can send multiple requests simultaneously that cause switchers to get out of shape. 4. Global buffer read overflow at X13 and X12 redfish. 5. Network IPv6 saving DNS Server IP as blank reverts to previous value; Auto Configuration fails to switch on once switched off. 6. Able to click blink or insert HDD button when in system lockdown mode. System Lockdown System Lockdown Storage Monitoring Physical View Eject / Insert button is not disabled. 7. It's a conflict checking rule on "Remote User" and "Remote Groups" while clicking on "Save" button in AD/LDAP. 8. Syslog packet did not follow RFC3164. 9. No pop-out error message when typing the wrong string at SNMPv2 Name field. 10. Network IPv6 saving DNS Server IP as blank reverts to previous value; Auto Configuration fails to switch on once switched off. 11. Disabled TLSv1.0 and TLSv1.1. 12. Sensor naming did not match with sensor specification. 13. It should replace "RMCP Port" with "IPMI Port" information from help content. 14. Virtual Media Floppy Disk help page did not match with actual web page. 15. UI Dashboard BIOS Firmware Version shows as 1.4b when it should be 1.5. 16. Component Info: Expanded PSU Table Text Inconsistency.

	<p>17. SUM tool couldn't get BIOS build date, but web and SMC IPMI Tool showed correctly.</p> <p>18. Failed to add valid Prefix length 128 for Static Route List.</p> <p>19. No MEL log after configuring the Mouse Mode setting.</p> <p>20. Downgraded from BIOS 1.3 to BIOS 1.1. BIOS is shown correctly, but IPMI web still shows BIOS 1.3.</p> <p>21. Support IPv6 enhancement spec. (Proposal for BIOS-BMC IPv6 inconsistency_V11.pptx)</p> <p>22. BMC version is incorrect in the troubleshooting Log.</p> <p>23. HDD info lines are not aligned at Physical View.</p> <p>24. Redfish Hostname special characters support.</p> <p>25. Downgraded from BIOS 1.5 to BIOS 1.1. BIOS is shown correctly, but IPMI web still shows BIOS 1.5.</p> <p>26. Needed to define MEL-ID for "LLDP was configured to enabled/disabled successfully."</p>
--	--