

IPMI Firmware Release Notes

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X13SEW-F/TF
Release Version	1.00.58
Build Date	7/13/2023
Previous Version	1.00.52
Update Category	Recommended
Dependencies	None
Important Notes	None
Enhancements	<ol style="list-style-type: none">1. Removed security_state feature. It should be available since 01.01.xx BMC firmware.2. Improved the one-shot passing rate in Redfish.Managers.Network Protocol automation test.
New features	N/A
Fixes	<ol style="list-style-type: none">1. Still prompt error tips when typed the path first and then the file server.2. Downgraded from BIOS 1.3 to BIOS 1.1. BIOS was shown correctly, but IPMI web still showed BIOS 1.3.3. SUM tool couldn't get BIOS build date, but web and SMC IPMI Tool showed normally.4. Failed to add valid Prefix length of 128 for Static Route List.5. Sensor reading did not match with SPEC.(Supermicro_BMC_Sensor_Naming_Guideline_2.4_Draft_03062023.xlsx)