

IPMI Firmware / BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	H13SVW-NT
Release Version	1.1
Release Date	09/27/2023
Build Date	09/27/2023
Previous Version	1.0
Update Category	Recommended
Dependencies	N/A
Important Notes	ECO #28830 BIOS Image: BIOS_H13SVW-1D22_20230927_1.1_STDsp.bin BIOS Update Package: BIOS_H13SVW-1D22_20230927_1.1_STDsp.zip Please update BIOS with attached Flash Utility in package.
Enhancements	N/A
New features	N/A
Fixes	1. Fixes Redfish automation test failed. 2. [AS-1115S-FWTRT] AOC-631102AC-ADAT port 2 cannot be detected under BIOS. 3. ID161750 - [AS-1015SV-WTNRT_EVT_H1_417](config4) Occur PST_BMC_SNSR_TOTAL sensor drop when execute DC onoff cycles.(Patch AOC-S25GC-i2S/i4S sensor lost issue.) 4. ID162504 - Fixes memory Detection error when the system plugs 2 DIMMs or 4 DIMMs in BIOS.

Release Notes from Previous Release(s)

Revision 1.0 (2023/08/25)

First release.