

## BIOS Release Notes Form

*Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.*

<b>Product Name</b>	<b>X13SCL</b>
<b>Release Version</b>	<b>1.1</b>
<b>Release Date</b>	<b>12/07/2023</b>
<b>Build Date</b>	<b>12/07/2023</b>
<b>Previous Version</b>	<b>1.0</b>
<b>Update Category</b>	<b>Recommended</b>
<b>Dependencies</b>	<b>None</b>
<b>Important Notes</b>	<b>None</b>
<b>Enhancements</b>	<ol style="list-style-type: none"><li>1. [BKCWW41] Updated Microcode 0xB0671 to 0x11F and 90672 to 0x34 per Intel Catlow BKC WW41.</li><li>2. [WW39] Upgraded SPS Tool version and FW from MFit_SPS_E3_06.02.04.006.0_kn3 to MFit_SPS_E3_06.02.04.008.0_kn3.</li><li>3. Fine tune get VPD data routines delay to avoid system trigger w/a and keep rebooting.</li><li>4. "System Mode: Deployed" was not displayed as expected when enabling Secure Boot.</li><li>5. Updated the Intel MRC to 0C.00.6B.41 per Intel Catlow BKC WW41. (3384.00)</li><li>6. Added BIOS setup keyword search function.</li><li>7. Grayed out "Preferred DNS server IP" and "Alternative DNS server IP".</li></ol>

	<ol style="list-style-type: none"> <li>8. The Intel RSTe name was removed and all RAID solutions in this product were branded as Intel VROC.</li> <li>9. Updated Intel Gigabit Lan driver to 9.8.09 (IBA 27.6).</li> <li>10. Fixed System - PNP (disable and enable) with IO.</li> <li>11. When set the Boot mode to Dual mode and Set the UEFI USB key to Boot Order#1 the system would hang up, and couldn't reset the system.</li> <li>12. Fixed Option ROM Messages, INT19 Trap Response, and Numlock on SUM GetCurrentBiosCfge.</li> <li>13. Default disable OOB send replace DisplayName feature to avoid that the SUM OOB test fail problem.</li> <li>14. Implemented Anti roll back for OOB that could power on after roll back ME.</li> <li>15. Triggered PERR SMBIOS Type 15 log will change the root port bridge to End-Device BDF.</li> </ol>
New features	None
Fixes	<ol style="list-style-type: none"> <li>1. Added when enable PCH PCIe swap function, and system reset the Early Video function can't be worked. (Default disable)</li> <li>2. SMBIOS Type 04 CPU current speed set the non-turbo mode.</li> <li>3. Fixed ME status will enter recovery mode when flashing the BIOS via afuefix64.efi.</li> <li>4. [SmcUefiBootsOptionRedfish] Made sure to assign unique ID for NVME device.</li> </ol>

***Release Notes from Previous Release(s)***

***1.0 (09/01/2023)***

1. *First release.*