

IPMI Firmware / BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	H12SSW-AN6
Release Version	01.03.01
Release Date	11/13/2023
Previous Version	01.01.17
Update Category	Recommend
Dependencies	N/A
Important Notes	ECO #29225 BMC_H12AST2600-ROT-E201MS_20231113_01.03.01_STDsp.bin Please update IPMI with attached Flash Utility in package.
Enhancements	N/A
New features	N/A
Fixes	[158656] [AOC-SLG4-2H8M2] The "Product Name/Firmware Revision" of M.2 drive couldn't be displayed correct under the BMC WebUI/Storage Monitoring page.

01.01.17 (

Factory Default enables IPv6

1.01.14(2022/07/01)

Factory Default enables IPv6

1.01.11(2022/03/16)

1. support AOC-S3816L-L16IT-O shown the AOC /HDD Temp in sensor reading via IPMI Web GUI

2. Support AOC-3908 shown the sensor reading via IPMI Web GUI

1.00.26(2021/10/05)

1. Fixed the BIOS golden image update failed issue.

1.00.23 (06/16/2021)

1. Fixes when system power on, IPMI GUI power control status still show red.

2. [PB#126433] fixes the AOC location is not in sequence.

3. [PB#126783] There is BMC SEL "Dedicated LAN Link Down - Assertion" during AC cycle stress.

4. [PB#125637] fixes the IPMI web can not read AIOM NIC temperature

5. [PB#122813] fixes the sensor name "AIOM" under tab "Network AOC" is different from tab "Sensor" Copy Project Issue Link

6. [PB#128391] fixes the AOC location info. (AOC-AG-i2M) is N/A Copy Project Issue Link

7. [PB#128412] fixes the Marvell controller (AOC-SLG2-2TM2) info and function are invalid in BMC WEB

1.00.20 (5/12/2021) First release