BMC Firmware Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X13DET-B
Release Version	1.02.14
Build Date	01/23/2024
Previous Version	1.02.06
Update Category	Recommended
Dependencies	None
Important Notes	None
Enhancements	None
New features	None
Fixes	 Set invalid IPv6 Static Address RAW command does not return CC. Fix OEM command switch IPv6 stateful mode will not auto get DHCP IPv6 IP. Updated Broadcom RAID Adapter FW Failed due to Failed to upload file. AIOM_NIC1 Temp dropped during cburn DC on/off test. [ENGINEERING] - Added NIC CPLD FirmwareInventory. IPMI ECO automation test failed. SmcNodeManager.ClearAllPolicies failed.