

IPMI Firmware Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	G1SMH-G
Release Version	01.02.09
Build Date	12/21/2023
Previous Version	01.02.02
Update Category	Recommended
Dependencies	BIOS R1.0a
Important Notes	IPMI Image: BMC_SCMAS2600-ROT20-2501MS_20231221_01.02.09_STDsp.bin IPMI Update Package: BMC_SCMAS2600-ROT20-2501MS_20231221_01.02.09_STD.ZIP Notes: The IPMI firmware should be updated via IPMI WebGUI.
Enhancements	1. NCSI re-scan and switch were treated as “Failover” during PWRON/PWROFF.
New Features	N/A
Fixes	1. Fixed the typo of AC Cycle endpoint. 2. Fixed the issue where there was a failure to enable and disable IPv6 autoconfig using the SMCIPMITool. 3. Fixed the issue where the IPMI user account lock couldn't work. 4. Fixed the issue where the redfish HI failed between BMC and BIOS. 5. Fixed the issue where Cburn LANPLUS interface was not accessible after “Shared AOC” was selected in WebGUI LAN interface. 6. Fixed the issue where there was only one dedicated option in LAN interface.

Release Notes from Previous Release(s)

01.02.02 (11/10/2023)

Initial Release