

BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	G1SMH
Release Version	1.1
Release Date	01/26/2024
Build Date	01/26/2024
Previous Version	1.0a
Update Category	Recommended
Dependencies	N/A
Important Notes	<p>BIOS Image: BIOS_G1SMH-1D10_20240126_1.1_STDsp.bin BIOS Update Package: BIOS_G1SMH-1D10_20240126_1.1_STDsp.ZIP</p> <p>Notes:</p> <ol style="list-style-type: none">1. BIOS was updated via IPMI Web GUI.2. To update the G1SMH BIOS, the BIOS_G1SMH-1D10_20240125_1.1_TESsp.bin must be applied to clear NVRAM. Follow the steps<ol style="list-style-type: none">1). Run the BIOS_G1SMH-D10_20240125_1.1_TESsp.bin file.2). Reboot the system.3). Run the BIOS_G1SMH-D10_20240126_1.1_STDsp.bin file.4). Reboot the system.
Enhancements	<ol style="list-style-type: none">1. Changed AMI RC from Label 17 to 19.2. Allowed HTTP Boot from AOC NIC via OOB.
New features	N/A
Fixes	<ol style="list-style-type: none">1. Fixed the issue where certain OOB functions could not work with BIOS 1.0c.2. Fixed the issue where BMC IPv6 Configuration in BIOS failed to function.3. Fixed the issue where a physical USB keyboard had to be removed and plugged in again to function during bootup.4. Fixed the issue where the driver interfered with OOB and a physical keyboard.

Release Notes from Previous Release(s)

1.0a (11/17/2023)

Initial Release