

BMC Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X13DEI-(T)
Release Version	01.02.02
Release Date	01/26/2023
Previous Version	01.01.07
Update Category	Enhancement
Dependencies	None
Important Notes	None
Enhancements	N/A
New features	1. Auto daylight saving function.
Fixes	1. Improved BMC efficiency, compatibility, and reliability. 2. Fixed CVE-2023-4879, CVE-2023-48795 and CVE-2023-33413. 3. Inlet Temp and M2_SSD threshold are incorrect.

Release Notes from Previous Release(s)

01.00.44 (02/03/2023) Initial release.
01.00.54 (05/23/2023) 1. [Fix] Fan sensor threshold is not match between SMCIPMITool and WEB 2. [Fix] Corrected PCH Spec Temp 3. [Fix] MEL log Description not quite match SNMPv3 Auth Protocol/ Private Protocol

- | |
|---|
| 4. [Fix] Host name can fill the 64 characters on BMC WebUI. |
| 5. [Fix] webGUI GPU tab info feature broken in 01.00.50 |
| 6. [Fix] U2_SSD temperature does not reflect the hottest sensor reading on IPMI |
| 7. [Enhancement] Modify Dedicated Link options: Add 1G Full and remove 10M Half/Full. |

01.00.58 (07/13/2023)

- | |
|--|
| 1. [Enhancement] Improve the one-shot passing rate in Redfish.Managers.Network Protocol automation test. |
| 2. [Enhancement] Remove weak cipher suite. |
| 3. [Enhancement] Fixed CVE-2023-33411 |
| 4. [Enhancement] Improved BMC efficiency, compatibility, and reliability. |

01.01.07 (10/27/2023)

- | |
|---|
| 1. [New] Disable IPMI Lan Port Interface |
| 2. [Enhancement] HTML5 Console as default |
| 3. [Enhancement] Dual mode for network setting as default |
| 4. [Enhancement] [MultVM] Virtual media support 3 CD/FLOPPY image mounting |
| 5. [Enhancement] Modify Dedicated Link options: Add 1G Full and remove 10M Half/Full. |
| 6. [Fix] Improved BMC efficiency, compatibility, and reliability. |

01.02.02 (01/26/2024)

- | |
|---|
| 1. [New] Auto daylight saving function. |
| 2. [Fix] Fixed CVE-2023-4879, CVE-2023-48795 and CVE-2023-33413 |
| 3. [Fix] Inlet Temp and M2_SSD threshold are incorrect. |
| 4. Improved BMC efficiency, compatibility, and reliability. |