

# **Notes to Release Notes Authors**

- *All fields must be completed; please indicate as “N/A” if not applicable.*
- *Release Notes should document functional changes, dependencies, bug fixes and added features.*
- *Release Notes must not mention the methods of implementation and/or internal processes.*
- *Release Notes must not mention of silicon errata and/or other external causations.*
- *Release Notes must not mention confidential/proprietary information and/or trade secrets of Supermicro or any third party.*
- *Please delete this page and the signature fields before submitting the document in PDF Format to Marketing for publication.*

# BMC Firmware Release Notes Form

*Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.*

<b>Product Name</b>	<b>X13DEG-R</b>
<b>Release Version</b>	<b>1.01.13</b>
<b>Release Date</b>	<b>01/20/2024</b>
<b>Build Date</b>	<b>01/20/2024</b>
<b>Previous Version</b>	<b>Final Release</b>
<b>Update Category</b>	<b>Critical</b>
<b>Dependencies</b>	<b>None</b>
<b>Important Notes</b>	<b>None</b>
<b>Enhancements</b>	<b>N/A</b>
<b>New features</b>	<b>N/A</b>
<b>Fixes</b>	<ol style="list-style-type: none"><li>1. [168423] [Beta IPMIECO] FAN speed no change between different fan modeCPLD icon no index under update page</li><li>2. [167025] [SYS-531A-I] BMC "sensor" page information is incorrect with BMC FW: 01.01.24</li><li>3. [167032] [SYS-551A-T] BMC "sensor" page information is incorrect with BMC FW: 01.01.24 (similar as #167025)</li><li>4. [165646] Digital battery reading check fail</li><li>5. [166300] CPLD2 manually recover function is not working under Platform Resiliency Action page.</li><li>6. [165538] [RoT] Recover NOR CDATA function test failed</li><li>7. [168423] [Beta IPMIECO] FAN speed no change between different fan mode</li></ol>

## *Release Notes from Previous Release(s)*

**01.01.13(01/20/2024)**

**1. First Release**

---

*Product Manager*

---

*Date*