

# BMC Firmware Release Notes Form

*Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.*

<b>Product Name</b>	<b>X12DPG-OA6</b>
<b>Release Version</b>	<b>01.04.16</b>
<b>Build Date</b>	<b>4/26/2024</b>
<b>Previous Version</b>	<b>01.04.12</b>
<b>Update Category</b>	<b>Recommended</b>
<b>Dependencies</b>	<b>None</b>
<b>Important Notes</b>	<ul style="list-style-type: none"><li>• <b>SMC-2024010010 Command Injection attack</b></li><li>• <b>SMC-2024010011 XSS attack</b></li><li>• <b>(CVE-2023-33413) SMC-2024010012 Command Injection attack</b></li><li>• <b>The BMC configuration file generated in BMC firmware older than Rev. 01.03.14 can't be imported.</b></li></ul>
<b>Enhancements</b>	<b>None</b>
<b>New features</b>	<ol style="list-style-type: none"><li>1. <b>[ENGINEERING] – Redfish supported BMC in each field v1.33/v1.34</b></li></ol>
<b>Fixes</b>	<ol style="list-style-type: none"><li>1. <b>[ENGINEERING] – X12 ALL sensor N/A in BMC 01.04.15.</b></li><li>2. <b>When a license is required, clicking Cancel redirects to dashboard. Should stay on same page, not redirect, or redirect to appropriate page for better user experience.</b></li></ol>

- |  |   |
|--|---|
|  | <ol style="list-style-type: none"><li>3. Updated the Backplane, Midplane, Fan/CPU/AIOM/AOM board CPLD. All should now present MEL ID with the MEL.</li><li>4. [GUI] "BMC Reset " help info page description is inconsistent with UI Spec and BMC web.</li><li>5. SNMP v3 description incorrect on the HELP page.</li><li>6. [ENGINEERING] - Upgraded MEL to 1.07 and added MEL 70&amp;368. [169763] - Recorded wrong MEL number when uploaded IPMI config unsuccessfully.</li></ol> |
|--|---|