



AMD Instinct™ MI300X Firmware Changes

Publication Number: 58759 v1.0 Release 24.12.08

Date: August 2024

Contents

Chapter 1: Introduction	3
Chapter 2: New Features	4
Chapter 3: Key Fixes	5
Appendix A Reference Documentation	6
Appendix B Notices	7
B.1 Trademarks	7

Chapter 1: Introduction

This document provides release notes for the AMD Instinct™ MI300X Accelerator firmware, including new features and key fixes.

★ **Important:** The MI300X Firmware 24.12 bundles require an upgrade to ROCm 6.2.

The *AMD Instinct™ MI300X Firmware Update Guide* provides instructions for updating the firmware of the MI300X system components.

Chapter 2: New Features

The new features in this release are listed below sorted by component.

Voltage Regulator (VR): Added new VR configs.

Chapter 3: Key Fixes

The following issues were fixed in this release.

- Updated VR settings to improve margin and stability.

Appendix A Reference Documentation

AMD Instinct™ MI300X Firmware Update Guide PID #58605

Appendix B Notices

© Copyright 2024 Advanced Micro Devices, Inc.

The information presented in this document is for informational purposes only and may contain technical inaccuracies, omissions, and typographical errors. The information contained herein is subject to change and may be rendered inaccurate for many reasons, including but not limited to product and roadmap changes, component and motherboard version changes, new model and/or product releases, product differences between differing manufacturers, software changes, BIOS flashes, firmware upgrades, or the like. Any computer system has risks of security vulnerabilities that cannot be completely prevented or mitigated. AMD assumes no obligation to update or otherwise correct or revise this information. However, AMD reserves the right to revise this information and to make changes from time to time to the content hereof without obligation of AMD to notify any person of such revisions or changes.

THIS INFORMATION IS PROVIDED "AS IS." AMD MAKES NO REPRESENTATIONS OR WARRANTIES WITH RESPECT TO THE CONTENTS HEREOF AND ASSUMES NO RESPONSIBILITY FOR ANY INACCURACIES, ERRORS, OR OMISSIONS THAT MAY APPEAR IN THIS INFORMATION. AMD SPECIFICALLY DISCLAIMS ANY IMPLIED WARRANTIES OF NON-INFRINGEMENT, MERCHANTABILITY, OR FITNESS FOR ANY PARTICULAR PURPOSE. IN NO EVENT WILL AMD BE LIABLE TO ANY PERSON FOR ANY RELIANCE, DIRECT, INDIRECT, SPECIAL, OR OTHER CONSEQUENTIAL DAMAGES ARISING FROM THE USE OF ANY INFORMATION CONTAINED HEREIN, EVEN IF AMD IS EXPRESSLY ADVISED OF THE POSSIBILITY OF SUCH DAMAGES.

B.1 Trademarks

AMD, the AMD Arrow logo, and combinations thereof are trademarks of Advanced Micro Devices, Inc.

Other product names used in this publication are for identification purposes only and may be trademarks of their respective companies.