

BMC FW Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X13DEG-QT
Release Version	1.02.06
Release Date	09/25/2024
Build Date	07/12/2024
Previous Version	1.01.09
Update Category	Critical
Dependencies	None
Important Notes	None
Enhancements	None
New features	1.Integrated Storelib8 to support AOC-S4116
Fixes	1.[174414] SYS-241H-TNRTTP - No log event shown in the maintenance event log when deactivating OOB license key with SUM in-band 2.[X13DEG-QT] Support GPU on slot 11 with 4U system by system PM request 3.Fix CVE-2023-4879 Terrapin Attack. 4.Fixed "IPv6 Ready Core Test" items issue. 5.[176669] ECO -- 21386 -- 01.02.04(20240419) -- Error message was not follow SW-PM defined when upload invalid TSIG file.

	6.[176667] ECO -- 21386 -- 01.02.04(20240419) -- SMCIPMITOOL -- Time zone will be changed after settings NTP Server 7.[176674] ECO -- 21386 -- 01.02.04(20240419) -- KVM reset return message is not follow SW-PM defined. 8.[176588] ECO -- 21386 -- 01.02.04(20240419) -- SMCIPMITOOL -- CPLD format is inconsistent between "ipmi raw 30 68 28 3" and "ipmi raw 30 68 29 3"
--	---

Release Notes from Previous Release(s)

1.01.09(11/20/2023)

1. Passed DMTF tool validation
2. 2022/Q1_Q2 Phase 1 (Ticket #299-00-220311-001) (<http://superform.supermicro.com/Home/WorkFlow/eForm/Preview?docId=c37217ed-e3d3-4915-a8b9-39c1b7b6098d>)
3. [160294] BETA -- 21386 -- 01.01.01(20230728) -- Can't press the save button when the ipmi lan function is to be switched to off
4. [160826] The GPU temp is going high by SRMS
5. [169150] ECO -- 21386 -- 01.01.05(20231221) -- [SUM] Fail to set SmartPower configuration by -c ChangeBmcCfg (ExitCode=149)
6. [169825][IPMI 01.01.05 ECO] IPMI automation test failed.

1.00.26(11/20/2023)

1. Fix NCSI IP missing report.

1.00.25(09/27/2023)

1. [162449]--The FAN 6 speed is always going high with BMC FW 1.00.23

1.00.23(08/21/2023)

1. [156774] "ECO -- 21386 -- 01.00.13 (2023/03/27) -- WEB -- Invalid sensor name."
2. [151493] "I2C re-mapping is Fail"
3. [152234] ECO -- 21386 -- 01.01.08 -- [MEL] No related MEL when setup Active Directory
4. [157111] BMC -- New Version displayed in WebGUI is incorrect when updating BIOS after Seamless Upgrade
5. [158276] Redfish Hostname special characters support
6. [158355] ECO-1386-01.00.16 (06/05/2023)-Function] Syslog packet not follow RFC3164.
7. [158352] ECO—21386—01.00.16 (06/05/2023)—[MEL-0036] format not quite match with Spec definition.
8. [158783] Redfish Automation test failed (w/ 8 failures.) on firmware v01.00.18
9. [159173] STD -- 17212 ? 01.01.01? [Security] Error format reply message at X13 and X12 redfish (/redfish/v1/AccountService/Accounts/{num})
11. [159950] IPMI ECO 33 Failed cases on Redfish automation.
12. [160826] The GPU temp is going high by SRMS

1.00.10 (02/24/2023)

1. [IPMI 01.00.08 ECO] SATC Redfish test failed.

2. *[IPMI 01.00.08 ECO] SMTP and SNMP can't receive some of SEL*
3. *[IPMI 01.00.09 ECO] There are no "Thermal trip " event log."*
4. *BMC Web Inventory Firmware page is not consistent with other project.*
5. *[152009] (X13DEG3.130_Signed , auto) Check Seamless Upgrade fail due to can't get correct version*

1.00.02 (11/25/2022)

1. *First Release*