

IPMI Firmware / BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	H12SSW-iNL/NTL (All)
Release Version	08.10.38
Release Date	10/17/2023
Previous Version	08.10.25
Update Category	Critical
Dependencies	N/A
Important Notes	ECO #30852 IPMI Image: BMC_H12SSW_iNNTL-B101MS_20231017_08.10.38_STDsp.bin Please update IPMI with attached Flash Utility in package.
Enhancements	Upgrade FW codebase to 8.10.38 from 3.10.38.
New features	N/A
Fixes	N/A

Release Notes from Previous Release(s) – these will be appended at the bottom of the current release notes in italic and in smaller print

Rev. 08.10.25 (03/22/2022)

Upgrade FW codebase to 8.10.25 from 8.10.08

Rev. 8.10.08 (4/15/2021)

1. Fixed issue IPMIECO test case 120 fail.
2. Fixed issue (#121872) ipmi command 0x30 0x80 1 2 return 0xCC.
3. Fixed can't update BIOS (Rome and Milan).

Rev. 8.10.05 (12/02/2020)

First release.