

# BIOS Release Notes Form

*Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.*

|                         |   |
|-------------------------|---|
| <b>Product Name</b>     | <b>H14SHM</b>   |
| <b>Release Version</b>  | <b>1.3</b>  |
| <b>Release Date</b>     | <b>03/04/2025</b>   |
| <b>Previous Version</b> | <b>1.0</b>  |
| <b>Update Category</b>  | <b>Recommended</b>  |
| <b>Dependencies</b>     | <b>IPMI 01.01.00.03</b>   |
| <b>Important Notes</b>  | <b>BIOS image: BIOS_H14SHM-1D6B_20250304_1.3_STDsp.bin<br/>BIOS Update package: BIOS_H14SHM-1D6B_20250304_1.3_STDsp.zip</b>   |
| <b>Enhancements</b>     | <b>1. Updated AMD Turin AGESA 1.0.0.3.<br/>2. Modified BIOS protect map from 64K-byte/bit to 4K-byte/bit.<br/>3. Added TurinPI_SP5_1003_Patch_1.</b>  |
| <b>New features</b>     | <b>N/A</b>  |
| <b>Fixes</b>            | <b>1. Fixed issue of Boot Override Device function can't work.<br/>2. Fixed issue of could not get BIOS attribute setting 'Secure Boot Mode' with optional 'GetCurrentBiosCfg'.<br/>3. Fixed issue of inconsistency in IPv6 Configuration Between BIOS and Web UI.<br/>4. Patched system diagnostics issue.<br/>5. Fixed issue where DNS IP show incorrect when set the DNS IP in Web.<br/>6. Fixed issue of SuperDiag F7 hot key no function.<br/>7. Fixed hang up during operating in AOC-S3916L-H16IR configuration utility.</b> |

*Release Notes from Previous Release(s)*

**1.0 (12/13/2024)**

First release.