

BMC Firmware Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X12DHM-6
Release Version	01.05.20
Build Date	3/14/2025
Previous Version	1.04.09
Update Category	Recommended
Dependencies	None
Important Notes	<ul style="list-style-type: none">• SMC-2024010010 Command Injection attack• SMC-2024010011 XSS attack• (CVE-2023-33413) SMC-2024010012 Command Injection attack• The BMC configuration file generated in BMC firmware older than Rev. 01.03.14 can't be imported.
Enhancements	None
New features	None
Fixes	<ol style="list-style-type: none">1. Stage BIOS fwUP with preserve_setting option, should preserve the BIOS setting.2. ADC voltage sensor names followed Supermicro_BMC_Sensor_Naming_Guideline_2.8.xlsx. For example, "12V" was changed to "MB 12V."3. [Help] Default port number for LDAP was 389 and 'SSL' LDAP was 636.