

IPMI Firmware

Super Micro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Super Micro and the Super Micro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2017 Super Micro Computer, Inc. All rights reserved.

Product Name	MBD-B1SD1-16C-TF-P MBD-B1SD1-TF-P MBD-B1SD2-16C-TF-P MBD-B1SD2-TF-P MBD-B1DRI-P MBD-B1SA4-2350F-P MBD-B1SA4-2750F-P MBD-B1SL1-F-P MBD-B1SL1-HF-P MBD-B2SS1-MTF-P MBD-B2SS2-MTF-P MBD-B2SS1-H-MTF-P MBD-B2SS2-H-MTF-P MBD-B2SS2-F-P MBD-B2SS1-CF-P MBD-B2SS1-CPU-P MBD-B2SS1-F-P
Release Version	2.61
Release Date	11/6/2017
Previous Version	2.56
Update Category	Recommended
Dependencies	None
Important Notes	N/A
Enhancements	N/A
New Features	<ol style="list-style-type: none"> 1. Added more power control records and BMC settings in Maintenance System Event Log (except for MBD-B2SS1-MTF-P, MBD-B2SS2-MTF-P, MBD-B2SS1-H-MTF-P, MBD-B2SS2-H-MTF-P MBD-B1SD1-16C-TF-P, MBD-B1SD1-TF-P, MBD-B1SD2-16C-TF-P, and MBD-B1SD2-TF-P). 2. Enabled login password to accept spaces. 3. Added more power control in system event log (except for MBD-B2SS1-MTF-P, MBD-B2SS2-MTF-P, MBD-B2SS1-H-MTF-P, MBD-B2SS2-H-

	<p>MTF-P MBD-B1SD1-16C-TF-P, MBD-B1SD1-TF-P, MBD-B1SD2-16C-TF-P, and MBD-B1SD2-TF-P).</p> <p>4. Added more system event logs under OOB license (except for MBD-B2SS1-MTF-P, MBD-B2SS2-MTF-P, MBD-B2SS1-H-MTF-P, MBD-B2SS2-H-MTF-P MBD-B1SD1-16C-TF-P, MBD-B1SD1-TF-P, MBD-B1SD2-16C-TF-P, and MBD-B1SD2-TF-P).</p> <p>5. Enabled username and password to accept special characters.</p>
<p>Fixes</p>	<p>1. Fixed inability NTP mode to get date time.</p> <p>2. Fixed incorrect Maintenance System Event Log date time (except for MBD-B2SS1-MTF-P, MBD-B2SS2-MTF-P, MBD-B2SS1-H-MTF-P, MBD-B2SS2-H-MTF-P MBD-B1SD1-16C-TF-P, MBD-B1SD1-TF-P, MBD-B1SD2-16C-TF-P, and MBD-B1SD2-TF-P).</p> <p>3. Fixed issue of Power/Temperature history record chart showing zero.</p> <p>4. Fixed failure of SOL stress test.</p> <p>5. Added support for setting/getting IP control command for SMCIPMITool.</p> <p>6. Fixed inability to get DHCP IP because of low priority of DHCP request.</p> <p>7. Fixed inability to generate logs in event log in IPMI 2.59.</p> <p>8. Fixed problem of OOB command version not being 0.</p>