

IPMI Firmware / BIOS Release Notes Form

Super Micro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Super Micro and the Super Micro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2017 Super Micro Computer, Inc. All rights reserved.

Product Name	X11DPH-I/T/TQ
Release Version	1.43
Release Date	12/18/2017
Previous Version	1.38
Update Category	Recommended
Dependencies	None
Important Notes	N/A
Enhancements	1. Improved multi-language content on the iKVM/HTML5 option menu and submenu.
New Features	1. Added new advance system event log.
Fixes	1. Fixed inability to change fan mode when default fan is in standard fan mode instead of PUE2 mode. 2. Added workaround for signal glitch issue caused by the I2C switch (U88) between PCH & SMBUS. 3. Fixed problem of IPMI web BIOS update not resetting the system. 4. Corrected Redfish APIs from /redfish/v1/Systems/1/Storage/HA-RAID/HA-RAID.[controller_num].Volume.[volume_num] to /redfish/v1/Systems/1/Storage/HA-RAID/Volumes/Controller.[controller_num].Volume.[volume_num] to

	correct Broadcom RAID volumes error.
--	---