

IPMI Firmware / BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X11DPU-XLL
Release Version	2.0a
Release Date	1/6/2018
Previous Version	2.0
Update Category	Critical
Dependencies	None
Important Notes	None
Enhancements	1. Set OC to 2.63% on 6154 and 6146 CPUs for better yield rate. 2. Updated 5.12_PurleyCrb_0ACFD084 for Purley Skylake platform PLR 3.1. 3. Updated SPS 4.00.04.294 PLR 3.1 PV version. 4. Updated CPU microcode SRV_P_217 for Skylake-EP H0/M0/U0 stepping CPUs.
New features	N/A
Fixes	1. Fixed problem of DMI being cleared when SUM LoadDefaultBiosCfg is run. 2. Fixed issue of system continuously rebooting when TPM module is plugged in.