

IPMI Firmware / BIOS Release Notes Form

Super Micro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Super Micro and the Super Micro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2017 Super Micro Computer, Inc. All rights reserved.

Product Name	X10DAL-i
Release Version	R2.0c
Release Date	10/02/2017
Previous Version	R2.0b
Update Category	Critical
Dependencies	None
Important Notes	None
Enhancements	<ol style="list-style-type: none"> 1. Updated Grantley Refresh RC 4.3.0. 2. Updated Broadwell-EP B0/M0/R0 CPU uCode MEF406F1_0B000021. 3. Updated Haswell-EP C0,1/M0,1/R2 CPU uCode M6F306F2_0000003A. 4. Updated Intel Server Platform Services 3.1.3 38.0 PLR7 for Grantley Refresh Platforms. 5. Updated SATA RAID OPROM/EFI driver to RSTe PreOS v4.6.0.1018 (RSTe package 4.6.0.1085). 6. Added tCCD_L Relaxation item under Memory Configuration menu. 7. Updated BIOS ACM 3.1.1 PW and SINIT ACM 3.1.1 PW. 8. Added Intel SPI vulnerability patch for Grantley.
New features	<ol style="list-style-type: none"> 1. Implemented SMC Recovery Flash Boot Block feature.
Fixes	<ol style="list-style-type: none"> 1. Added a patch for the issue of the screen not lighting automatically after waking up from S3 by pressing the Power Button in Windows 10. 2. Fixed problem of display having no output when secure boot is enabled.

Notes

- All fields must be completed; please indicate as "N/A" if not applicable.
- Release Notes should document functional changes, dependencies, bug fixes and added features.

- *Release Notes must not mention the methods of implementation and/or internal processes.*
- *Release Notes must not mention of silicon errata and/or other external causations.*
- *Release Notes must not mention confidential/proprietary information and/or trade secrets of Super Micro or any third party.*

Release Notes from Previous Release(s) – these will be appended at the bottom of the current release notes in italic and in smaller print

