## **IPMI Firmware / BIOS Release Notes Form**

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X11DPT-PS
<b>Release Version</b>	2.0b
Release Date	02/24/2018
Previous Version	2.0
Update Category	Critical
Dependencies	None
Important Notes	None
Enhancements	1. Updated CPU microcode to address CVE-2017-5715 security patch
	issue.
	2. Updated Purley RC 151.R03.
New features	1. Changed RC default setting to upgrade POST Memory correctable error to uncorrectable error and map out the channel.
Fixes	1. Patched for inability of AOC-MH25G-b2S2G to show sensor.
	2. Disabled CPU2 IIO PCIe root port ACPI hot plug function.
	3. Fixed inability of AOC-MTG-i4T to show sensor.
	4. Fixed problem of SMC skipping first boot option in UEFI mode when
	retrying boot.
	5. Fixed inability to reset the system under DOS by pressing "Ctrl-Alt-
	Del" on USB keyboard when "Port 60/64 Emulation" is disabled.
	6. Fixed inability of some CPUs to display correct microcode revision

under BIOS setup menu.