

IPMI Firmware / BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X10SRM-F/TF
Release Version	3.0a
Release Date	2/8/2018
Previous Version	3.0
Update Category	Critical
Dependencies	None
Important Notes	None
Enhancements	1. Updated CPU microcode to address 'Spectre' variant 2 (CVE 2017-5715) security issue. 2. Changed BIOS revision to 3.0a. 3. Updated SATA RAID OPROM/EFI driver to RSTe PreOS v4.7.0.1014. 4. Updated Intel Server Platform Services 3.1.3.50 for Grantley Refresh Platforms. 5. Removed support for using Ctrl+home to trigger recovery. 6. Changed Memory correctable threshold to 100 and enabled Cloaking for Broadwell CPU E5-26xx SKU.
New features	N/A
Fixes	1. Fixed problem of system not prompting "iKVM doesn't support add-on VGA device. Please change the D-SUB connector to Add-on VGA device..." on POST screen when setting VGA priority to

	<p>"Offboard".</p> <p>2. Fixed failure of UEFI OS to boot or install when disabling BMC by motherboard jumper "JPB1" or by setting "BMC Support" to Disabled via BIOS setup.</p>
--	--