

IPMI Firmware / BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X10DRH(-I/LN4+/T4+)
Release Version	3.65
Release Date	12/15/2017
Previous Version	3.58
Update Category	Recommended
Dependencies	None
Important Notes	None
Enhancements	1. Improved multi-language content on the iKVM/HTML5 option menu and submenu. 2. Disabled MCTP support on Broadcom 3108 firmware so it only supports I2C protocol.
New features	1. Added support for NVIDIA V100.
Fixes	1. Fixed problem of M10 GPU temperature being too high. 2. Fixed failure of SUM "Test_case_215 Outband - ChangeBmcCfg and compare". 3. Fixed inability to disable LDAP Authentication immediately after enabling it. 4. Fixed incorrect product number. 5. Fixed problem of system hanging at POST stage, IERR occurring,

	<p>and some affiliated HDDs within 3108 being lost when systems installed with 3108 AOC run cburn ON/OFF test.</p> <p>6. Fixed failure of SUM 2.0.1 Test.</p>
--	---