

## IPMI Firmware

*Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.*

<b>Product Name</b>	<b>X11DPU(+)</b>
<b>Release Version</b>	<b>1.47</b>
<b>Release Date</b>	<b>3/13/2018</b>
<b>Previous Version</b>	<b>1.43</b>
<b>Update Category</b>	<b>Critical</b>
<b>Dependencies</b>	<b>N/A</b>
<b>Important Notes</b>	<b>N/A</b>
<b>Enhancements</b>	<b>N/A</b>
<b>New features</b>	<b>1. Added Intel OTA feature to fix failure of SMC OOB TPM Provisioning via IPMI feature for customized provisioning table.</b> <b>2. Enabled AC Power On Event log.</b> <b>3. Set AC Power On Event log to be reported when BMC executes cold reboot.</b> <b>4. Added Redfish memory information feature.</b>
<b>Fixes</b>	<b>1. Fixed incorrect power readings on "power consumption" page.</b> <b>2. Changed UTC zone time by SMCIPMITool commands.</b>