

IPMI Firmware / BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X11DPU-XLL
Release Version	2.0b
Release Date	3/14/2018
Previous Version	2.0
Update Category	Critical
Dependencies	None
Important Notes	None
Enhancements	1. Implemented enhancement to address ‘Spectre’ variant 2 (CVE 2017-5715) security Patch issue. 2. Set OC to 2.38% on 6154 and 6146 CPUs for better yield rate. 3. Changed BIOS revision to 2.0b. 4. Updated 5.12_PurleyCrb_0ACFD084 for Purley Skylake platform PLR 3.1. 5. Updated SPS 4.00.04.294 PLR 3.1 PV version.
New features	N/A
Fixes	1. Fixed failure of BIOS ECO ATT test case 306. 2. Fixed problem of DMI being cleared when SUM LoadDefaultBiosCfg is run. 3. Fixed issue of system continuously rebooting when TPM module is

	plugged in.
--	--------------------