

IPMI Firmware / BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	B11QPI-T
Release Version	3.49
Release Date	03/16/2018
Previous Version	3.48
Update Category	Recommended
Dependencies	None
Important Notes	None
Enhancements	N/A
New features	N/A
Fixes	1. Fixed failure of SUM UpdateRaidController command on latest firmware of AOM-B3108-H8-B11. 2. Fixed incorrect web reading for 64G DIMM capacity. 3. Fixed failure of CMM to set correct switch port speed on 25G switch. 4. Fixed issue of CPU1 reading -1 and other sensor readings disappearing after Cburn on/off stress testing. 5. Fixed incorrect power history record after AC cycle stress test. 6. Fixed failure of IPMICFG to change BMC MAC. 7. Removed FanMode from Blade BMC Redfish API because Blade