

IPMI Firmware

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X10DRT-B+
Release Version	3.70
Release Date	3/21/2018
Previous Version	3.68
Update Category	Recommended
Dependencies	None
Important Notes	None
Enhancements	N/A
New features	1. Set system event log to record most configuring operations.
Fixes	1. Fixed failure of SMCIPMITool "pminfo" command on firmware 3.68. 2. Fixed incorrect power history record after AC cycle stress test. 3. Fixed typo errors on Factory Default page, on System Event Log page, in language file of "Power Consumption", on BIOS Update page, on SMC RAKP page, on Activate License page, in XPath /html/body/table/tbody/tr[5]/td[2]/ul/li[1]/span, and in language file of key "LANG_SERVER_HEALTH_ADV_CAPTION". 4. Fixed problem of Remote Control -> HDD/SSD Power Control showing "Not present" in 6NVME. 5. Fixed problem of too many system event logs breaking BMC.