

## IPMI Firmware / BIOS Release Notes Form

*Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.*

<b>Product Name</b>	<b>H11DSi/H11DSi-NT</b>
<b>Release Version</b>	<b>1.34</b>
<b>Release Date</b>	<b>6/5/2018</b>
<b>Previous Version</b>	<b>1.27</b>
<b>Update Category</b>	<b>Critical</b>
<b>Dependencies</b>	<b>N/A</b>
<b>Important Notes</b>	<b>IPMI Image SMT_H11AST2500_134</b>
<b>Enhancements</b>	<b>1. Adjusted the SOCRUN threshold for all H11 projects.</b>
<b>New features</b>	<b>1. Added AMD-specific OEM command set 0x30 0x80 to read the current package power of CPU and set safe package power of CPU.</b>

Fixes	<ol style="list-style-type: none"> <li>1. Fixed failure of Redfish Automation Tool.</li> <li>2. Shortened the waiting time for the BMC to control the FAN speed when BMC starts.</li> <li>3. Fixed problem of GPU1 appearing in BMC Web sensor list when GPU card is not installed.</li> </ol>
-------	--

*Release Notes from Previous Release(s) – these will be appended at the bottom of the current release notes in italic and in smaller print*

N/A
-----