

## IPMI Firmware / BIOS Release Notes Form

*Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.*

|                         |   |
|-------------------------|---|
| <b>Product Name</b>     | <b>K1SPi(-T)</b>  |
| <b>Release Version</b>  | <b>2.0a</b>   |
| <b>Release Date</b>     | <b>12/31/2017</b>   |
| <b>Previous Version</b> | <b>2.0</b>  |
| <b>Update Category</b>  | <b>Recommended</b>  |
| <b>Dependencies</b>     | <b>None</b>   |
| <b>Important Notes</b>  | <b>None</b>   |
| <b>Enhancements</b>     | <b>1. Updated CPU microcode SRV_P_224 for A0 (Knights Mill) &amp; B0 (Knights Landing).</b> |
| <b>New features</b>     | <b>N/A</b>  |
| <b>Fixes</b>            | <b>N/A</b>  |

***Release Notes from Previous Release(s)***

***2.0 (11/29/2017)***

- 1. Updated RC to 02.00.01.*
- 2. Updated Knights Landing microcode to 0x1B0 and Knights Mill microcode to 0x11.*
- 3. Updated ME to 03.01.03.030.*
- 4. Added SPI vulnerability patch solution (HW Sequencing Support).*
- 5. Fixed issue with PCH temperature alert.*