

IPMI Firmware / BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X11SSW-(4)TF
Release Version	2.2
Release Date	5/24/2018
Previous Version	2.1a
Update Category	Critical
Dependencies	None
Important Notes	None
Enhancements	1. Changed BIOS revision to 2.2. 2. Updated CPU microcode to address 'Spectre' derivatives (CVE-2018-3639 & CVE-2018-3640) security issue. 3. Updated Kaby Lake BIOS ACM 1.4.0 and SINIT ACM 1.3.0. 4. Enhanced ability to enter setup menu without password when system only has Administrator password.
New features	N/A
Fixes	1. Fixed problem of Afu /O command clearing SMC SMBIOS region (\$SMC). 2. Implemented workaround for problem of IP displaying 0.0.0.0 information the first time AC powers on BMC.

	<p>3. Fixed problem of the system hanging when trying to create virtual driver on LSI3108 storage card under BIOS setup.</p> <p>4. Fixed missing reminding string "iKVM doesn't support add-on VGA device..." when VGA is plugged in & "Primary Display"=="PEG".</p>
--	--

Release Notes from Previous Release(s) – these will be appended at the bottom of the current release notes in italic and in smaller print