

IPMI Firmware

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X11SAT-F
Release Version	1.50
Release Date	10/5/2018
Previous Version	1.15
Update Category	Recommended
Dependencies	N/A
Important Notes	N/A
Enhancements	1. Improved multi-language content on the iKVM/HTML5 option menu and submenu. 2. Renamed Redfish APIs as follows: from /redfish/v1/UpdateService/SSL to /redfish/v1/UpdateService/SSLCert, and from /redfish/v1/UpdateService/SSL/Actions/SSL.Upload to /redfish/v1/UpdateService/SSLCert/Actions/SSLCert.Upload.
New features	1. Added Redfish memory information feature. 2. Added 204 and 405 http status code support for Redfish API: 204 http status code responds to APIs that support PATCH 405 http status code responds to APIs that do not support PATCH 3. Show nested ICANN domain in "OEM" if there is data. 4. Added support for SEL circular buffer. 5. Changed naming rule for 10G/40G. 6. Added support for GPU threshold in GPU thermal guide 1.09.

	7. Added support for HTML5. 8. Misc WebGUI improvements.
Fixes	1. Multi-language support for iKVM/HTML5 console help page. 2. Corrected timeout of Invalid Default Active Directory. 3. Corrected problem with sometimes inability to login on web page. 4. Correct VCPU Upper Non-Recoverable going high log occurring in system IPMI-SEL. 5. Corrected incorrect behavior of DCMS enabling Syslog function and read Syslog without OOB key. 6. Failed DIMM locations now match motherboard silkscreen. 7. Digit keys now work in French keyboard layout. 8. Corrected Dynamic DNS enable function. 9. OOB License no longer disappears when updating firmware. 10. Removed unexpected IPMI events during RHEL 7.x installation. 11. Corrected some failures of gateway change. 12. Corrected some failures of UID Control function. 13. Unified SNMP behavior with X11DP.