

## IPMI Firmware / BIOS Release Notes Form

*Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.*

<b>Product Name</b>	<b>H11SSW-iN/NT (All)</b>
<b>Release Version</b>	<b>1.42</b>
<b>Release Date</b>	<b>01/28/2019</b>
<b>Previous Version</b>	<b>1.38</b>
<b>Update Category</b>	<b>Critical</b>
<b>Dependencies</b>	<b>N/A</b>
<b>Important Notes</b>	<b>ECO #21798 IPMI Image SMT_H11AST2500_32M_142 Please update IPMI image with attached Flash Utility in package.</b>
<b>Enhancements</b>	<b>N/A</b>
<b>New features</b>	<b>N/A</b>
<b>Fixes</b>	<b>1. Fixed problem of the LAN temperatures remaining high and fan speed staying at high RPM. 2. Fixed problem of the CPU throttling value setting.</b>

*Release Notes from Previous Release(s)*

--