

IPMI Firmware / BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X11QPH+
Release Version	1.64
Release Date	1/16/2019
Previous Version	1.63
Update Category	Recommended
Dependencies	None
Important Notes	None
Enhancements	N/A
New features	N/A
Fixes	1. Fixed problem of WebUI disappearing after selecting simplified Chinese language.

Release Notes from Previous Release(s)

1.63 (1/04/2019)

- 1. Added GPU temperature sensor reading on X11QPH.*
- 2. Fixed problem of DCMS license activation showing inconsistent results between IPMI firmware 1.52 and 1.61.*
- 3. Fixed inability of CPU VRM to drive fans on X11QPH.*

Product Manager

Date