IPMI Firmware / BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X11OPi
Release Version	3.0a
Release Date	
	03/08/2019
Previous Version	2.1a
Update Category	Critical
Dependencies	None
Important Notes	None
Enhancements	1.Update Intel Reference Code to BKC WW04 Rev: RC0571.D03.
	2.Update Intel Xeon Micro-code for Skylake-EP.
	3.Add Purley platform refresh A0 Stepping CPU Support.
	4.Add Purley platform refresh B0 Stepping CPU Support.
	5.Add Purley platform refresh B1 Stepping CPU Support.
	6.Update RSTe VMD/SATA/sSATA driver to v6.0.0.1024.
	7.Update Intel Server Platform Services 04.01.04.251.0 for Purley-Refresh Platforms.
	8.Update Intel BIOS ACM Firmware to v1.7.1 and SINIT ACM Firmware to v1.7.1.
	9.Enable RFC4122 UUID support.
	10.Add Tesla T4 GPU Support.
New features	N/A
Fixes	N/A

Release Notes from Previous Release(s)

2.1a (02/11/2019)

1.Update RSTe VMD/SATA/sSATA driver to v5.5.0.1028.

2. Updated Intel Management Engine Firmware to Address CVE-2018-3643 Security Issue.

3.Update for QPI correctable error.

4.Updae memory threshold to 512.

5.Hide WHEA errors from proc source.

6.Update for BMC UCE log.

7.Update for X-AMI string and fix SUM TC220 and TC308 failure issue.