

IPMI Firmware / BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X11QPH+
Release Version	3.0c
Release Date	3/20/2019
Previous Version	3.0a
Update Category	Recommended
Dependencies	None
Important Notes	None
12	1. Added support for Purley Refresh platform. 2. Update Intel Reference Code to BKC WW08 Rev: RC0578.D07. 3. Update Intel Xeon Micro-code for Skylake-EP. 4. Update Intel Server Platform Services 04.01.04.256.0 for Purley-Refresh Platforms. 5. Update Intel BIOS ACM Firmware to v1.7.1 and SINIT ACM Firmware to v1.7.2. 6. Update for new VRM.
New features	N/A
Fixes	N/A

Release Notes from Previous Release(s)

3.0a (1/23/2019)

- 1. Added support for Purley Refresh platform.*
- 2. Update Intel Reference Code to BKC WW02 Rev: RC0568.D10.*
- 3. Update Intel Xeon Micro-code for Skylake-EP.*
- 4. Update Intel Server Platform Services 04.01.03.239.0 for Purley-Refresh Platforms.*
- 5. Update Intel BIOS ACM Firmware to v1.7.1 and SINIT ACM Firmware to v1.7.1.*
- 6. Enable RFC4122 UUID support.*
- 7. Add Tesla T4 GPU Support.*
- 8. Update RSTe VMD/SATA/sSATA driver to v6.0.0.1024.*