

IPMI Firmware Notes

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X10DRH-I/C/IT/CT
Release Version	3.81
Release Date	5/28/2019
Previous Version	3.80
Update Category	Recommended
Dependencies	None
Important Notes	None
Enhancements	N/A
New features	1. Enabled logging multiple HDDs as absent at the same exact second as a StorageController type event in order to remind the user about possible component-related problem (e.g., storage controller, cable, or backplane error). 2. Added support for NVidia T4, RTX 5000, 6000, and 800.
Fixes	N/A

Release Notes from Previous Release(s)

3.80 (2/14/2019)

- 1. Migrated the IPMI Event Log to the URL "redfish/v1/Systems/1/LogServices" in Redfish and changed the name "Event Log" to "Health Event Log" in Redfish and Web UI.*
- 2. Added patch for CVE-2019-6260 pantsdown.*
- 3. Fixed problem of degraded & unavailable SEL event appearing after Broadcom 3108 firmware is updated.*
- 4. Fixed incorrect number of spaces between two words.*
- 5. Fixed inability to set NM power policy by Redfish API.*
- 6. Fixed failure to add AD group name and domain in SMCIPMITool.*
- 7. Fixed inability to open Java IKVM when domain name is used to login to BMC.*
- 8. Fixed problem when duplicate events related to BRCM3108 occur at the same time.*